



# STATE OF NEW YORK DEPARTMENT OF HEALTH

*Day*

Office of Public Health

11 University Place

Albany, New York 12203-3399

Barbara A. DeBuono, M.D., M.P.H.  
Commissioner

Karen Schimke  
Executive Deputy Commissioner

October 5, 1995

Benedict Salanitro, P.E.  
Superintendent of Public Works  
Village of Tarrytown  
232 West Main Street  
Tarrytown, NY 10591-3199

RE: Log No. 10533  
Corrosion Control Study  
for Village of Tarrytown  
(V) Tarrytown, Westchester County

Dear Mr. Salanitro:

Our office has reviewed the study referenced above and respectfully put forth the following:

1. Provide our office with entry point iron levels and/or manganese levels which require the sequestration of a poly ortho phosphate blend.
2. The residual phosphate is insufficient as proposed. A residual of 2-3 ppm of phosphate will be required for optimum corrosion control.
3. How was the theoretical 90th percentiles given in graphs III-C and III-D arrived at?
4. Provide our office with copies of all original data used for the study.

Once we receive the above items, you may anticipate a three day turn-around on the designation of optimum corrosion control for your system. In the meantime, if you have any questions, please contact our office at (518) 458-6756.

Sincerely,

Michael J. Montysko  
Assistant Sanitary Engineer  
Bureau of Public Water Supply Protection

bs/95279PRO0004

cc: Westchester County Health Department, Attn: Mr. Paccione  
NYSDOH, Attn: Mr. Stasko